

0037



EarthFax

EarthFax
Engineering, Inc.
Engineers/Scientists
7324 So. Union Park Ave.
Suite 100
Midvale, Utah 84047
Telephone 801-561-1555
Fax 801-561-1861
www.earthfax.com

April 4, 2007

Pamela Grubaugh-Littig
Utah Division of Oil, Gas and Mining
Coal Program
1594 West North Temple, Suite 1210
Salt Lake City, UT 84114-5801

Subject: Emery Mine, Federal Lease IBC, Clean Copy (electronic version)

Dear Pam:

John Gefferth of Consol Energy asked that I forward the enclosed CDs containing PDF versions of the recently revised text and maps associated with the Emery Mine Federal Lease Incidental Boundary Change. One copy of the CD is for your files and the other is for your submittal to OSM.

Please contact Mr. Gefferth at 618-825-6850 if you have any questions concerning this submittal.

Sincerely,

Richard B. White, P.E.
President

Cc: John Gefferth

Enclosure

Inventory OK
4/15/2007

RECEIVED

APR 05 2007

DIV. OF OIL, GAS & MINING